

January Monthly Report

Wednesday, January 29, 2025

School Wayne Car Class Advanced Car Number

Monthly Report

The first thing we worked on this year on the A107 was bodywork. After last year's championship race, we had some fixes to make. First, we straightened the body to how it had been before the race. Then once the body was straight, we sanded down the body so we could put new fiberglass patches on to strengthen the side of the body. Next, we sanded down the fiberglass to make it smooth. Last we added body filler to make the side super smooth and ready for paint, we did have to sand it down one last time before painting the car.



A107 with body repairs completed.



We are now on to the painting of the A107, we have chosen a color shift paint for the car. To start we had to apply a base coat of gloss black, for the best look when we get to the actual final color shift paint.

